

## PREPPING ULTRASOUND FOR ENTERING PATIENT ROOM



Ensure that all required transducers, as well as all necessary procedural equipment is ready. Empty the carrying caddy (The receptacle attached to the rear of the cart, ensuring that there are no supplies other than a supply of **single use gel packets or a single gel bottle, and several Green top wipes**



Perform precautionary wipe of all surfaces with GREEN TOP wipe

## CLEANING ULTRASOUND FOR PASSING OUT OF THE ROOM BEFORE REMOVING PPE



Sanitize Gloves with Alcohol Gel



Visually inspect the machine for any bodily fluid or tissue  
- If present, remove with wet gauze or wipes



Wipe all surfaces with a **green top wipe** and keep visibly wet for 1 minute, Recommended cleaning schedule:

60 seconds	<input type="checkbox"/> Monitor	<input type="checkbox"/> Touchscreen
60 seconds	<input type="checkbox"/> Probes and cords	<input type="checkbox"/> Probe wells
60 seconds	<input type="checkbox"/> Cart and basket	<input type="checkbox"/> handle
60 seconds	<input type="checkbox"/> Gel bottle	<input type="checkbox"/> Wipe bottle
60 seconds	<input type="checkbox"/> Power cord	

## PASSING ULTRASOUND OUT OF THE ROOM AND SECOND CLEANING



Out of room provider dons full PPE, including mask and eye protection

While out of room provider opens door, in-room provider (still wearing PPE) should use foot to roll the U/S to the out of room provider. Be careful to avoid excessive contact with door.



Visually inspect the machine for any bodily fluid or tissue.  
**If present, remove with wipes**



Wipe all surfaces with a **green top wipe** and keep visibly wet for 1 minute, recommended cleaning schedule:

60 seconds	<input type="checkbox"/> Monitor	<input type="checkbox"/> Touchscreen
60 seconds	<input type="checkbox"/> Probes and cords	<input type="checkbox"/> Probe wells
60 seconds	<input type="checkbox"/> Cart and basket	<input type="checkbox"/> handle
60 seconds	<input type="checkbox"/> Gel bottle	<input type="checkbox"/> Wipe bottle
60 seconds	<input type="checkbox"/> Power cord	<input type="checkbox"/> <b>Wheels</b>



Maintain wet for 1 minute before considering the device decontaminated  
**If blue wipes used, all cleaning schedules above / surface wet times are increased to 3 minutes**

Wipe any residue from the screen



Dispose of PPE in appropriate container