



* Refer to IC & Patient Management Guidance for Covid -19

Applying (Donning) PPE

1	Gather Supplies <ul style="list-style-type: none"> • PAPR - or - mask (surgical or N95) & eye protection • Yellow isolation gown • 1 Pair Nitrile gloves
2	Remove Jacket, ID, Cell Phone
3	Perform Hand Hygiene
4	PAPR ONLY: <ul style="list-style-type: none"> • Clip Battery to Waist (pocket, pants or belt) • Plug PAPR Cord into Battery • Confirm air flow and lights
5	Don Face Protection <ul style="list-style-type: none"> • Surgical mask & eye protection, - or - • N95 mask & eye protection, - or - • PAPR (adjust ratchet to a snug fit)
6	Don Isolation Gown
7	Don Clean Gloves

Removing (Doffing) PPE

1	Sanitize Gloved Hands
2	Remove Isolation Gown <ul style="list-style-type: none"> • Roll into Ball • Discard into Soiled Linen Bin
3	Remove Gloves and Perform Hand Hygiene
4	Exit Patient Room
5	Perform Hand Hygiene
6	Don Clean Gloves
7	Remove Eye Protection & Disinfect
8	Remove PAPR or Mask
9	Disinfect PAPR
10	Remove Gloves and Wash Hands